




VIBO
Wire processing

Charge maxi:
Maximum load:
Portata massima:
Maximale belastbarkeit:
Carga maxima:
Obciążenie maksymalne:

30
Kg


Notice de montage
Assembling instructions
Istruzioni di montaggio
Montageanleitung
Instrucoes de montagem
Manual de montaje
Instrucja montazu





PETGS402MC



15 min.



1



AVANT DE COMMENCER, SE REPORTER AUX CONSEILS DE MONTAGE EN ANNEXE

BEFORE STARTING, REFER TO THE ASSEMBLING ADVICE IN ANNEX


PRIMA DI COMINCIARE, VEDERE I CONSIGLI DI MONTAGGIO

VOR DIE MONTAGE, BITTE BEILIEGENDE ANWEISUNGEN FOLGEN


ANTES DE COMERÇAR, ADIARSE AOS CONSELHOS DE MONTAGEM EM ANEXO

ANTES DE EMPEZAR CONSULTE LOS CONSEJOS PARA EL MONTAJE


PRZED ROZPOCZECIEM ZAPOZNAC SIE ZALACZONA INSTRUKCJA MONTAZU




A x 1




B-C x 1




D x 2




E x 4



F x 4






G x 16




H x 2




I x 2




IV



V



VI



VI

